
## Analog Meter Static Removal 51ATIC

The manufacturer takes precautions to eliminate static from all Analog Meters before shipment. If you experience erratic needle behavior follow one of these steps.



1 Mix a solution of 1 part liquid dish soap with 4 parts water and wipe on the meter cover.

2. Spray an antistatic solution on meter cover

2650-883X-10 Rev. B